

Thermoplastic Markings

Installation Guide



1
Clean application area thoroughly by removing all sand, dirt, chemicals and oily substances, measure & mark.



2
Using a suitable propane torch, remove any moisture present and preheat the area prior to treatment. Use a suitable primer on non-asphalt and aggregate rich surfaces. Allow primer to dry.



3
Remove the packaging and carefully place the marking onto the prepared surface, with the glass-coated top facing up. Position as accurately as possible and cut to size if required.



4
Heat the marking using a suitable propane torch keeping the flame approximately 20-40cm from the marking. Do not concentrate the heat in one area. Instead, heat with an even sweeping action. Heat until it starts bubbling and flowing into the surface.



5
The marking should cool and harden within 5-10 minutes. When cooled, examine the marking and test by trying to lift. If areas do lift, repeat step 4. Finally, if additional drop on glass is required, re-heat to make the surface tacky and add anti-slip glass.